

Product Safety Recall



SUNSEEKER 2.0M AWNING (Part No.32132)

SUNSEEKER 2.5M AWNING (Part No. 32133)

**Supplied by Rhino Rack Australia and its dealers from
26th March 2021 to 15 July 2021**

Defect: The bolts that attach the awning to the vehicle's roof may shear off, causing the awning to detach from the vehicle.

Hazard: If the awning detaches there is an increased risk of serious injury or death to vehicle occupants, other road users or bystanders.

What to do: Consumers should immediately remove the awning from their vehicle and contact the place of purchase or Rhino Rack for replacement bolts.

Contact Details: Rhino Rack Australia Pty Limited, Tel: 02 8846 1900 Mon-Fri 8:30am-5:00pm AEST, email recall@rhinorack.com.au , or go to www.rhinorack.com.au. Alternatively, contact the place of purchase.

**See productsafety.gov.au for
Australian product recall information**