




RHINO-RACK PIONEER VEHICLE FITTING INFORMATION

	PION	EER	CONNECTOR	HEIGHT ADDED (mm/in)						
TOYO	521	01	SX100	103 / 4.1						
VEHICLE NOTES	- Do not operate sunroof									
REGION	AUS	NZ	USA	CA	SA	UK	EU	ZA		
AVAILABILITY	×	×	✓	✓	×	×	×	×		
RUNNING DATES	-	-	2021 -	2021 -	-	-	-	-		










BAR NO.	Α	В	С	D	E	F	G
DIMENSION (CM)	-50	0	50				
SPACERS REQ'D							
CONNECTOR	SX		SX				



NOTES FOR DEALERS / FITTERS

It is your responsibility to ensure these fitting instructions are given to the end user or client.

Document No: R2840 Issue No: 1 Issue Date: 20-May-21